


FIG. 1






FIG. 3





FIG. 4

CERTIFICATE OF DESTRUCTION


1 Date of Destruction May 12, 2004, at 3:00 pm

2 Picture of destroyed hard disk

Overall view



Enlargement of
manufacturing number portion



3 Worker

Name

OO OO

Picture



4 Place of destruction Kobe plant

5 Apparatus employed for destruction Second machine

6 Reason for destruction because ***

FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG.10




FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B




FIG. 15




FIG. 16

A rectangular certificate form with a thin black border. At the top center, it says "CERTIFICATE OF DESTRUCTION". To the right of the text, a leader line points to the number "7". The form contains the following information:

ABC corporation

1. Date of destruction February 1, 2005, at 2:00 pm

2. ID code of destroyed recording medium
17-2-1-0052

3. Image data of destroyed recording medium
stored in attached CD

4. Destruction worker
OO OO

5. Place of destruction
ABC plant

6. Apparatus employed for destruction
second machine HA-4000

FIG. 17





FIG. 18







FIG. 19

FIG. 20






FIG. 23





FIG. 24






FIG. 25




FIG. 26

FIG. 27A




FIG. 27B

